

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave. St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-004773**Date Inspected:** 16-Nov-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1330**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 2230**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name:	NA			CWI Present:	Yes	No	
Inspected CWI report:	Yes	No	N/A	Rod Oven in Use:	Yes	No	N/A
Electrode to specification:	Yes	No	N/A	Weld Procedures Followed:	Yes	No	N/A
Qualified Welders:	Yes	No	N/A	Verified Joint Fit-up:	Yes	No	N/A
Approved Drawings:	Yes	No	N/A	Approved WPS:	Yes	No	N/A
				Delayed / Cancelled:	Yes	No	N/A

Bridge No: 34-0006**Component:** OBG Fabrication**Summary of Items Observed:**

Caltrans Quality Assurance (QA) Inspector, Mr. Paul Dawson, arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China, for the purpose of monitoring welding and fabrication of the San Francisco / Oakland Bay Bridge (SFOBB) components. The QA Inspector observed the following:

OBG Bay #7

This QA Inspector performed random final visual and ultrasonic (UT) inspections of Floor Beam welds

FB016-022-045, FB019-020-043, FB015-024-045, FB010-011-045

FB015-023-045, FB011-017-045, FB009-017-043. The QA Inspector observed the welds that were ultrasonically inspected by this QA Inspector appear to comply with AWS D1.5 UT requirements. For additional information on these inspections see the TL6027 Ultrasonic Test Report.

Heavy Bay #1

The QA Inspector performed random AWS D1.5 visual and ultrasonic inspections of tower Skin A welds

SSD1-SA164E/F-9A/B, SSD1-SA164D/F-31A/B, SSD1-SA164D/F-9A/B and SSD1-SA164D/F-16A/B as listed on the ZPMC Notification of Witness Inspection document #1425 and the welds appear to comply with project specifications. For additional information on these inspections see the TL6027 Ultrasonic Test Report.

ZPMC ultrasonic Inspection personnel have rejected welds SSD1-SA164D/F-16, SSD1-SA164D/F-4,

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SSD1-SA164D/F-25, SSD1-SA164D/F-28, SSD1-SA164E/F-20, SSD1-SA164E/F-25, SSD1-SA164E/F-31 and SSD1-SA164E/F-1. For additional information on these inspections see the TL6027 Ultrasonic Test Report.

Summary of Conversations:

See above.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco 13816942685, who represents the Office of Structural Materials for your project.

Inspected By:	Dawson,Paul	Quality Assurance Inspector
Reviewed By:	Carreon,Albert	QA Reviewer
